

A Division of Chavis Enterprises, LLC

MDE ONSITE SEWAGE DISPOSAL SYSTEM (OSDS) OPERATING INSPECTION FORM

Client Information																		
Name Jenniger Staab						Phone Number 443-8				3-86	-865-5021							
Street Addı	Street Address 2429 Harkins Road						Ema	Email staabtr			truc	ruckingllc@gmail.com						
City White Hall						Stat	State MD			Zip Code 21161								
					(Genera	l Info	rn	ation	ì								
Property Address 19701 Old York Road																		
City White Hall							Stat	State MD Zip Code						21161				
County Baltimore							Date	Date and Time of Inspection 08/09/2023 12:00							00 PM			
Inspector N	Inspector Name Heath Vinck						Con	Company Chavis Septic Services										
Office Pho	Office Phone 410-838-1200						Fax Number 410-838-3001											
Mobile Pho	Mobile Phone 410-940-9377						Ema	Email heath@chavisenterprisesllc.com										
Property T	perty Type Residential				Age	of Dwe	lling	ling 83 Years Number of				of F	Bedrooms		3			
Occupied?	cupied? No If Vacant						w Lor	Long? Unknown Rental?						No	No			
Number of People Moving Ur					ıknowr	Н	Homeowner Interview Conduc					uct	red? No					
OSDS Records Requested from County?					Yes	Wer	Were Records Available? Partial											
Current We	eathe	r	Sunny				Precipitation in past 48 hours 0"											
OSDS History																		
How Long	Has	Ow	vner Owned t	he l	Proper	ty?	Unknown											
Number of	Peop	ole	in Dwelling 1	now	v 0													
Age of OSI	DS?	L	Jnknown															
Any History of Sewage Problems? No																		
If Yes, Detail Problems Below:																		
Pumping Frequency Unknown Last D									Date 1	Pu	mped	[Unknov	wn				
Any Repairs to OSDS? Unknown																		
If Yes, Detail Repairs (Include Dates):																		

CHAVIS SEPTIC SERVICES

Septic Tank/ Pretreatment										
Туре	1		Construction							
☐ Septic ☐ Cesspool ☐ Holding Tank ☐ BAT ☐ Other:			 □ Concrete □ Metal □ Plastic □ Other: Cinder Block 							
Condition		Note if Present								
 □ Acceptable □ Acceptable with Concern □ Unacceptable □ Needs Further Evaluation 		e lber)	☐ Headworks Box☐ Sand Filter☐ Low Pressure Pipe☐ Drip Tubing☐ At-Grade Mound☐ Sand Mound							
Was Septic Tank Located? Yes □ Grease Trap □ Sand Mound										
If Pre-Treatment Unit, Note Current Service Provider N/A										
Describe Access to Septic Tank Mahole Riser										
Depth of Tank Below Grade 12"										
Liquid Level in Tank (below normal/ normal/ above normal) Normal										
Any Evidence of Elevated Leve	els of	Sewage	In the Past?	N	0					
Was Sludge Sample Collected?	' No)								
If Yes, Total Liquid Depth N	I/A	Sl	Α	S	N/A					
During Septic Tank Pump Out	ny Flow	Back Obse	rom	Field S	ystem	Did no	t Pump			
After Pump Out, Is Structural In	ntegri	ity of the	e Tank Inter	or Ac	cepta	able?	No (Cinder Bl	ock Tank)	
Presence of Inlet Baffle Verified and Condition Acceptable? Yes										
Presence of Outlet Baffle Verified and Condition Acceptable? Yes										
Septic Tank Observations:										
The current septic tank is constructed from cinder blocks. Access to the septic tank was through a manhole riser installed to grade. The lid of the manhole riser was found cracked and broken. Due to the fact that the septic tank is constructed from cinder blocks it is considered unacceptable due to its age, likelihood of not being water tight and its structural integrity. The cinder block tank will need to be pumped and abandoned. A pre-cast concrete top seam septic tank will need to be installed by a licensed septic contractor.										
Overall Condition of Septic Tank: Unacceptable										

CHAVIS SEPTIC SERVICES

Pump Tank															
		Type				Condition									
	Yes No				inder luent	☐ Acceptable with Conce									
Comme	nts:		1												
Soil Absorption System															
		e					Condit	ion							
 □ Drain Fields □ Dry Well □ LPD □ Drip □ Sand Mount □ Other: 								 ☐ Acceptable ☐ Acceptable with Concerns ☐ Unacceptable ☐ Needs Further Evaluation 							
Trenches (Number) 0 Total Length N/A Width N								N/A	Depth	N/A					
Seepage Pits/ Drywells (Number) 2 Diameter 6' & 8									6' & 8'	Depth	6' & 8'				
Was Distribution Box Located? No (Serial Connection)															
Method	Method of Locating Distribution Box N/A														
Does the Distribution of Effluent Appear to be Equal? Serial Connection															
Was Soil Absorption System Located? Yes															
Are Observation Ports Present/ Functional?								Yes							
Was Hydraulic Load Test Performed? Yes															
If Yes, Volume of Water Introduced to System 50 Gallons															
Soil Absorption System Observations:															
We were able to located 2 dry wells at the time of the inspection. Each of the dry wells are hooked in a serial connection. The first dry well in the connection was found to be 6' in depth with a diameter of 6'. There was currently 32" of operating room remaining inside of the dry well before the effluent will begin to flow to the second dry well. The second dry well in the connection was found to be 8' in depth with a diameter of 8'. The second dry well was found to be completely dry. A very small hydraulic load test was completed and confirmed that the effluent was making it from the septic tank to the first dry well but since the wastewater level is still below the effluent line leaving the first dry well we could not confirm that the effluent would flow from the first dry well to the second dry well. Overall Condition of Soil Absorption System: Acceptable															



Inspection Summary

The septic system located at 19701 Old York Road in White Hall, Maryland 21161 was inspected on Thursday August 10th, 2023 at approximately 12:00 PM. The current septic tank is constructed from cinder blocks. Access to the septic tank was through a manhole riser installed to grade. The lid of the manhole riser was found cracked and broken. Due to the fact that the septic tank is constructed from cinder blocks it is considered unacceptable due to its age, likelihood of not being water tight and its structural integrity. The cinder block tank will need to be pumped and abandoned. A pre-cast concrete top seam septic tank will need to be installed by a licensed septic contractor. We were able to located 2 dry wells at the time of the inspection. Each of the dry wells are hooked in a serial connection. The first dry well in the connection was found to be 6' in depth with a diameter of 6'. There was currently 32" of operating room remaining inside of the dry well before the effluent will begin to flow to the second dry well. The second dry well in the connection was found to be 8' in depth with a diameter of 8'. The second dry well was found to be completely dry. A very small hydraulic load test was completed and confirmed that the effluent was making it from the septic tank to the first dry well but since the wastewater level is still below the effluent line leaving the first dry well we could not confirm that the effluent would flow from the first dry well to the second dry well.

Overall Condition of Septic System: Unacceptable

OSDS Layout

Show a diagram of the OSDS layout relative to the house. Include well location, street location, driveway and other pertinent site features as well as all OSDS piping and components.





- Any septic system component will not be considered accessible if it is below 16" of grade. It will not be uncovered during inspection and further excavation costs may be required in the case it must be uncovered to complete inspection (if information cannot be otherwise gathered).
- This inspection report indicates the present condition of the private on-site subsurface sewage disposal system based on recommended inspection procedures outlined in this report. The results of this inspection do not guarantee or warranty future performance.
- This is a visual inspection only and based on many unseen components and factors.
- If the house in concern is unoccupied, this report may not be truly accurate. Little to no use on a septic system can allow time to clear problems that would otherwise arise.
- If a system is rated "acceptable", it does not guarantee that the system will meet the local approving authority's criteria for determining compliance with state codes.
- If the ground condition is wet at the time of inspection, it is possible that ground moisture can cover and hide otherwise visual problems, causing a false reading and rating of system.
- The recipient of this report should discuss any deficiencies found by this inspection with the Inspector.
- Chavis Septic Services always recommends that the septic tank is pumped during the inspection. If the septic tank is not pumped during the inspection Chavis Septic Services will not be able to throughly inspect the structural integrity or condition of the septic tank. If the customer chooses to opt out of the septic tank pumping during the inspection Chavis Septic Services will not be held responsible for any later discoveries with the structural integrity of the septic tank.

I attest that the information contained herein, and my assessment is honest, thorough, and, to my knowledge, correct. Furthermore, I have completed an MDE approved course in the proper inspection procedures and have fully applied the standards of practice taught in the course during this inspection.

MDE Certified Inspector Signature	Heath Vinck

CHAVIS SEPTIC SERVICES

