

# HOME LAND

## ENVIRONMENTAL

Location	Inspector
521 Dutrow Road Westminster MD 21157	Nicholas Riehl Environmental Inspector



Friday, December 13, 2024

The camera was inserted into the front line via the access cap in the basement. The front line is composed PVC and the camera did not encounter any obstructions in the line. Due to the depth of the system and bushes above the tank, the camera was unable to view the back line. No water was available on the property to conduct a hydraulic load test.

This is a subjective and visual inspection only, based upon many unknown and unseen factors. This report does not WARRANT nor Guarantee continued functional septic system operations. Payment and/or use of this evaluation signify understanding and acceptance of the above clauses. Please see separate septic report for further information.

### Pipe Composition & Explanations:

PVC pipe- May be installed if property is newer than 1982 and can last over 100 years. PVC is impervious to root penetration however, a crack or a joint that is not properly sealed can allow root intrusion. Generally white or green in color.



Access to the sewer

1' 6"



Start of the front line.

0"



Bend in the line.

4' 6"



End of the line. The camera has reached the septic tank.

12' 11"