MARYLAND DEPARTMENT OF THE ENVIRONMENT			
		) INSPECTION CERTIFICATE	NO. 589338
27/374 03-26-18-6242-045 KING HENRY PROPERTIES LLC MDE TRACKING NO. MDE PROPERTY NO. (Include county code prefix,)  OWNER NAME  OWNER NAME			
MDE TRACKING NO.	MDE PROPERTY NO. (Include count	y code prefix,) OWNER NAME	
15 S. KRESSON ST.		BALTIMORE 21224	1900
Street Address	Unit No.	City Zip Code	County Property Construction Date
The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only <b>ONE</b> category and method are to be marked. The following attachments are required to be submitted with the certificate: Form E for Lead Free. Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams for Modified Risk Reduction. The certificate shall be signed by the inspector who performed the inspection. Inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "00000" if Property Construction Date is unknown. Lead paint inspection contractors <b>must</b> mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794.  INSPECTION CATEGORIES			
1. Lead Free	2. Full Risk Reduction	3. Modified Risk Reduction	5. Lead Safe
Methods	Methods	Methods	Methods
A. One Time Only (Interior & Exterior)	A. Dust Inspection	B. Visual Inspection and Dust	A. Dust Inspection
OR	OR	Inspection	OR  B. Dust Inspection and Visual Inspection
	□ <b>D.</b> Dust Inspection		OR
B. Limited (Interior Lead Free Only)	with Exterior Waiver	C. Visual Inspection <u>and</u> Dust Inspection with Exterior Waiver	C. Dust Inspection with Lead Free Exterior
Passing Re-inspection required no later than:	Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04 / 30 /	Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04/30/ unless otherwise noted in local	D. Dust Inspection and Visual Inspection with Lead Free Exterior  AND
Number of Pre-1950 Lead Free Units	unless otherwise noted in local code.  OR	code.	Verification that windows are lead free or have
Number of Post-1949 Lead Free Units	E. Dust Inspection with Lead Free Exterior	D. Visual Inspection and Dust Inspection with Lead Free Exterior	been treated so friction surfaces are lead free.
PASSED Based on the findings of the attached inspection report(s), I certify that the property unit meets the certification criteria at this time. (circle property or unit)			
FAILED Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit)			
I certify that I inspected the above listed property/unit on 46/12 at 2:45 a.m. fr.m. Inder Title 6, Subjitle 8 of the Environment Article, Annotated Code of MD.			
KEUIN & Janes Kuin Franco 10196 7-25-2013 Kur I Janes 10197 7-25-2013			
Inspector's Name Inspector's Signature Accreditation No. Accreditation Exp. Date Inspection Contractor Name Accreditation No. Accreditation Exp. Date			
Form Number: MDE 330, Revised 40/2011 (copy distribution: original to owner; yellow to MDE; pink to tenant; goldenrod to inspection contractor)			