| MARYLAND DEPARTMENT OF THE ENVIRONMENT 935364 LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO | | | | | |
|--|--|---|---|--|--|
| | 26 37 4179 G IDE PROPERTY NO. (Include count | | GOAL | 15 LL | C |
| 3507 Cliftmon | A AVA 22 Eloor | Baltimore | 21213 | | 1943 |
| The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per unit processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection | | | | | |
| contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794. INSPECTION CATEGORIES | | | | | |
| 1. Lead Free | 2. Full Risk Reduction | 3. Modified Risk R | eduction | 5. Lead | Safe |
| Methods | Methods | Methods | | | Methods |
| ☐A. One Time Only (Interior & Exterior) OR | A. Dust Inspection OR | ☐B. Visual Inspection and Inspection OR | <u>I</u> Dust | ☐A. Dust Insp | ection OR ection and Visual Inspection |
| ☐B. Limited (Interior Lead Free Only) Passing Re-inspection required no later than: // Number of Pre-1950 Lead Free Units Number of Post-1949 | D. Dust Inspection with Exterior Waiver | C. Visual Inspection and | C. Visual Inspection and Dust Inspection with Exterior Waiver | | OR ection with Lead Free Exterior OR |
| | Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than 04 / 30 / | Passing Re-inspection (Form D Statement of Work) required no 04/30/ unless otherwise no | later than | with Lead Free I A Verification that windo | ection <u>and</u> Visual Inspection d Free Exterior AND |
| | Unless otherwise noted in local code. OR E. Dust Inspection with | OR D. Visual Inspection and | | | t windows are lead free or have friction surfaces are lead free. |
| Lead Free Units Lead Free Exterior Inspection with Lead Free Exterior PASSED Based on the findings of the attached inspection report(s), I certify that the property/unit meets the certification criteria at this time. (circle property or unit) | | | | | |
| FAILED Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit) | | | | | |
| I certify that I inspected the above listed property/unit on 16/23/21 at 10:00 a.m/p.m. under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD. | | | | | |
| Inspector's Name Inspector's Sign | | | Contractor Name | 1523 | |