, · ·	MARYLAND DE				735793
LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO					
0304571	032506 7086021	<u> </u>	Angelozzi & Mi	ccomicu Ent	erprises
AND THE RESERVE OF THE PARTY OF	MDE PROPERTY NO. (Include	_		R NAME	.000
3610 Browning		Baltimore	21225	Balticity	1926
Street Address	Unit N	No. City	Zip Code	County	Property Construction Date
The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per unit processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794. INSPECTION CATEGORIES					
1. Lead Free	2. Full Risk Reducti	on 3. Modifie	d Risk Reduction	5. Lead	l Safe
Methods	Methods	N	1ethods	Man althorach mar are years	Methods
✓A. One Time Only (Interior & Exterior) OR □B. Limited (Interior Lead Free Only)	OR D. Dust Inspection with Exterior Waiver	□B. Visual Inspection □C. Visual Insp	or OR	□ A. Dust Inspection OR □ B. Dust Inspection and Visual Inspection OR □ C. Dust Inspection with Lead Free Exterior OR	
Passing Re-inspection required no later than: // Number of Pre-1950 Lead Free Units Number of Post-1949 Lead Free Units	Passing Re-inspection (Form D an Supervisor Statement of Work) required no later than 04 / 30 / unless otherwise noted in local cool OR Description E. Dust Inspection with Lead Free Exterior	Statement of Work 04/30 / unless of code. D. Visual Insp	on (Form D and Supervisor required no later than otherwise noted in local OR ection and Dust with Lead Free Exterior	with Lea	d Free Exterior AND at windows are lead free or have a friction surfaces are lead free.
PASSED Based on the findings of the attached inspection report(s), I certify that the property unit meets the certification criteria at this time. (circle property or unit)					
FAILED Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit)					
I certify that I inspected the above listed propert vanit on 5 /18 /16 at 9:00 a.m/p.m under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.					
Zvi Pollach 3. Ru	13816	11-24-2016	Quality Inspect		
Inspector's Name Inspector's S	ignature Accreditation No.	Accreditation Exp. Date	Inspection Contractor Name	Accredita	tion No. Accreditation Exp. Date

Form Number: MDE 330, Revised: 10/2013

(copy distribution: original to owner; yellow to MDE; pink to tenant; goldenrod to inspection contractor)