LEAD PAINT RISK RED		ARTMENT OF THE ENVIROR O INSPECTION CERTIFICATE		632551
2/00 173 0320032293 003 501 NORTH ROSE ST LLC				
- 1 1	MDE PROPERTY NO. (Include cou	nty code prefix.) OWNER NAM		1010
3915 Edmonds	Unit No.	City Zip Code	County	Property Construction Date
Street Address	Chit ivo.	Eny Zip Code	County	Troperty Construction Date
The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form E for Lead Free. Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams for Modified Risk Reduction. The certificate shall be signed by the inspector who performed the inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794. INSPECTION CATEGORIES				
1. Lead Free	2. Full Risk Reduction	3. Modified Risk Reduction	5. Le	ad Safe
Methods	Methods	Methods		Methods
☐ A. One Time Only (Interior & Exterior) OR ☐ B. Limited (Interior Lead Free Only) Passing Re-inspection required no later than:	OR D. Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work)	□ B. Visual Inspection and Dust Inspection OR □ C. Visual Inspection and Dust Inspection with Exterior Waiver Passing Re-inspection (Form D and Supervisor Statement of Work) required no later than	C. Dust In	OR Inspection and Visual Inspection OR Inspection with Lead Free Exterior OR Inspection and Visual Inspection
Number of Pre-1950 Lead Free Units Number of Post-1949 Lead Free Units	required no later than 04 / 30 / unless otherwise noted in local code. OR DE. Dust Inspection with Lead Free Exterior	OR D. Visual Inspection and Dust Inspection with Lead Free Exterior	Verification	that windows are lead free or have so friction surfaces are lead free.
PASSED Based on the findings of the attached inspection report(s), I certify that the property unit meets the certification criteria at this time. (circle property or unit) FAILED Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit)				
I certify that I inspected the above listed property/unit on 1 113 at 3 :// a.m./p.m. under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD. OSALE Will Am Sw Paste Will Am Sw Paste Will Paste Will Am Sw Past				

Form Number: MDE 330, Revised: 10/2011