

# MARYLAND DEPARTMENT OF THE ENVIRONMENT

898912

## LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO.

0313529  
MDE TRACKING NO.

04131318350192  
MDE PROPERTY NO. (Include county code prefix.)

HIPOLITO C. VIDAL  
OWNER NAME

1000 DOWNTON RD. Single BALTIMORE 21227 BALTIMORE 0148  
Street Address Unit No. City Zip Code County Property Construction Date

The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per unit processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection. Inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794.

### INSPECTION CATEGORIES

☐ 1. Lead Free

Methods

☐ A. One Time Only  
(Interior & Exterior)  
OR

☐ B. Limited  
(Interior Lead Free Only)  
Passing Re-inspection  
required no later than:  
\_\_\_\_/\_\_\_\_/\_\_\_\_

Number of Pre-1950  
Lead Free Units \_\_\_\_\_

Number of Post-1949  
Lead Free Units \_\_\_\_\_

☒ 2. Full Risk Reduction

Methods

☒ A. Dust Inspection  
OR

☐ B. Dust Inspection  
with Exterior Waiver  
Passing Re-inspection (Form D and  
Supervisor Statement of Work)  
required no later than 04/30/\_\_\_\_  
unless otherwise noted in local code.  
OR

☐ E. Dust Inspection with  
Lead Free Exterior

☐ 3. Modified Risk Reduction

Methods

☐ B. Visual Inspection and Dust  
Inspection  
OR

☐ C. Visual Inspection and Dust  
Inspection with Exterior Waiver  
Passing Re-inspection (Form D and Supervisor  
Statement of Work) required no later than  
04/30/\_\_\_\_ unless otherwise noted in local  
code.  
OR

☐ D. Visual Inspection and Dust  
Inspection with Lead Free Exterior

☐ 5. Lead Safe

Methods

☐ A. Dust Inspection  
OR

☐ B. Dust Inspection and Visual Inspection  
OR

☐ C. Dust Inspection with Lead Free Exterior  
OR

☐ D. Dust Inspection and Visual Inspection  
with Lead Free Exterior  
AND  
Verification that windows are lead free or have  
been treated so friction surfaces are lead free.

☒ PASSED Based on the findings of the attached inspection report(s), I certify that the property unit meets the certification criteria at this time. (circle property or unit)

☐ FAILED Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit)

I certify that I inspected the above listed property unit on 4/14/20 at 8:00 a.m./p.m. under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Muhammad I. Nasir  
Inspector's Name Inspector's Signature  
4255 2145122 Competent Home Inspections 13235 2123121  
Accreditation No. Accreditation Exp. Date Inspection Contractor Name Accreditation No. Accreditation Exp. Date

Form Distribution: original to owner; yellow to MDE; pink to tenant; goldenrod to inspection contractor