MARYLAND DEPARTMENT OF THE ENVIRONMENT LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO. 657589							
O310805 MDE TRACKING NO.  O320090701012 MDE PROPERTY NO. (Include county code prefix.)  OWNER NAME							
MDE TRACKING NO.  2203 EAGLE ST	EAGLE ST 2208: SFP BALTO 21223			ER NAME		1920	
Street Address	Unit No.	City	Zip Code	Coun	ty Pro	perty Construction Date	
Street Address	Cinc No.	City .	Zip couc	Coun	110	perty Constituction Date	
The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only <b>ONE</b> category and method are to be marked. The following attachments are required to be submitted with the certificate: Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams collected for Modified Risk Reduction. Form E for Lead Free, which shall include a \$10 per unit processing fee for each certificate. To be paid to: P.O. Box 1417, Baltimore, MD 21203. The certificate shall be signed by the inspector who performed the inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors <b>must</b> mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794.  INSPECTION CATEGORIES							
1. Lead Free	2. Full Risk Reduction	3. Modifie	d Risk Reduction		5. Lead Safe		
Methods	Methods		lethods	Washing	Methods		
A. One Time Only	A. Dust Inspection	B. Visual Inspe			A. Dust Inspection		
(Interior & Exterior)		Inspection	etion and Dust	LA.		R	
OR	OR		OR	<b>□</b> B.	B. Dust Inspection and Visual Inspection		
<b>☑B.</b> Limited	D. Dust Inspection	C. Visual Inspe		ПС.	OR  C. Dust Inspection with Lead Free Exterior		
(Interior Lead Free Only) Passing Re-inspection	with Exterior Waiver	Inspection v	vith Exterior Waiver			R	
required no later than:	Passing Re-inspection (Form D and		on (Form D and Supervisor	□D.	D. Dust Inspection and Visual Inspection		
4 /30/16	Supervisor Statement of Work) required no later than 04 / 30 /		required no later than therwise noted in local		with Lead Free E		
Number of Pre-1950	unless otherwise noted in local code.	code.		Verif		ND ws are lead free or have	
Lead Free Units	OR		OR			surfaces are lead free.	
Number of Post-1949 Lead Free Units	E. Dust Inspection with Lead Free Exterior	D. Visual Inspection	ection <u>and</u> Dust with Lead Free Exterior				
PASSED Based on the findings of the attached inspection report(s), I certify that the property unit meets the certification criteria at this time. (circle property or unit)							
FAILED Based on the findings of the attached inspection report(s), the property/unit fails to meet certification criteria at this time. (circle property or unit)							
I certify that I inspected the above listed property unit on 4 /30 / 14 at 3 : 30 a.m. p.m. under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.							
J. M. CABLE ON CLE 4320 3/2/16 LEADTEC 4329 3/2/16 Inspector's Name Inspector's Signature Accreditation No. Accreditation Exp. Date Inspection Contractor Name Accreditation No. Accreditation Exp. Date							
Inspector's Name Inspector's Sig	gnature Accreditation No. Accr	editation Exp. Date	nspection Contractor Name		Accreditation No.	Accreditation Exp. Date	

Form Number: MDE 330, Revised: 10/2013