

MARYLAND DEPARTMENT OF THE ENVIRONMENT

LEAD PAINT RISK REDUCTION (MDE FORM 330) INSPECTION CERTIFICATE NO. 624604

0304571
MDE TRACKING NO.

0325067274 011K
MDE PROPERTY NO. (Include county code prefix.)

Angelozzi, McCormick Enterprises LLC
OWNER NAME

930 E. Patuxent
Street Address

2
Unit No.

Baltimore
City

21225
Zip Code

Balt City
County

1943
Property Construction Date

The Maryland accredited lead inspector must mark an inspection category 1, 2, 3, or 5 and mark the appropriate inspection method. Only ONE category and method are to be marked. The following attachments are required to be submitted with the certificate: Form E for Lead Free. Form C, laboratory results, and diagrams for Full Risk Reduction, and Forms B and C, original signed copy of Supervisor's Statement of Work, laboratory results, and diagrams for Modified Risk Reduction. The certificate shall be signed by the inspector who performed the inspection. Inspection certificates and all required attachments must be submitted to MDE within 10 days following Lead Free and Lead Safe Inspections and within 10 days following the receipt of dust sample results for Full and Modified Risk Reduction Inspections. Copies of all inspection records shall be maintained for at least 5 years by lead inspection contractors. Maximum penalties will be pursued by MDE for any falsified documentation that is received by MDE. Indicate "0000" if Property Construction Date is unknown. Lead paint inspection contractors must mail inspection certificates and the supporting documentation for inspection certificates to: P.O. Box 943, Jessup, MD 20794.

INSPECTION CATEGORIES

1. Lead Free

2. Full Risk Reduction

3. Modified Risk Reduction

5. Lead Safe

Methods

A. One Time Only
(Interior & Exterior)
OR

B. Limited
(Interior Lead Free Only)
Passing Re-inspection
required no later than:
____/____/____

____ Number of Pre-1950
Lead Free Units
____ Number of Post-1949
Lead Free Units

Methods

A. Dust Inspection
OR

D. Dust Inspection
with Exterior Waiver

Passing Re-inspection (Form D and
Supervisor Statement of Work)
required no later than 04/30/____
unless otherwise noted in local code.

E. Dust Inspection with
Lead Free Exterior

Methods

B. Visual Inspection and Dust
Inspection
OR

C. Visual Inspection and Dust
Inspection with Exterior Waiver

Passing Re-inspection (Form D and Supervisor
Statement of Work) required no later than
04/30/____ unless otherwise noted in local
code.

OR

D. Visual Inspection and Dust
Inspection with Lead Free Exterior

Methods

A. Dust Inspection
OR
 B. Dust Inspection and Visual Inspection
OR
 C. Dust Inspection with Lead Free Exterior
OR

D. Dust Inspection and Visual Inspection
with Lead Free Exterior
AND

Verification that windows are lead free or have
been treated so friction surfaces are lead free.

PASSED Based on the findings of the attached inspection report(s), I certify that the property (unit) meets the certification criteria at this time. (circle property or unit)

FAILED Based on the findings of the attached inspection report(s), the property (unit) fails to meet certification criteria at this time. (circle property or unit)

I certify that I inspected the above listed property (unit) on 1/16/2013 at 10:00 a.m. p.m. under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Zvi Pollack 3-11-11
Inspector's Name Inspector's Signature
13810 11-29-2014
Accreditation No. Accreditation Exp. Date
Quality Inspections 9830 11-29-2014
Inspection Contractor Name Accreditation No. Accreditation Exp. Date