
From: Rebecca Elliott -HCHD- <rebecca.elliott1@maryland.gov>

Sent: Friday, December 19, 2025 12:12 PM

To: Marcelle Hodges <mhodes@garceaurealty.com>

Subject: Re: 7 Lake Drive well yield test

Hi Marcelle,

I was able to speak with our Regional MDE Consultant about the above well evaluation. The well was determined to be acceptable, however repairs to the well casing will be required as a requirement of the Certificate of Occupancy (C of O) for the building permit application as furncos are not considered acceptable casing extensions.

Once the previously mentioned requirements for the building permit application have been satisfied, we can proceed with the review process. Please let me know if you have any additional questions.

Thank you and have a good weekend,