

MARYLAND DEPARTMENT OF THE ENVIRONMENT

LEAD PAINT RISK REDUCTION (MDE FORM 330)

INSPECTION CERTIFICATE NO. 1049928

0389194

0308254178E022

MDE TRACKING NO.

MDE PROPERTY NO.

Juan Johnson Altra Group

OWNER NAME

03208 LYNDAL AVE

Street Address

BALTIMORE

City

Baltimore city

County

21213

Zip Code

1923

Construction Year

PASSED

Inspection Status

Unit No.

Full Risk Reduction

Inspection Category

Dust Inspection

Inspection Method

Re-Inspection required no later than

Certificate Expiration Date

Invalid

Invalidated Date

I certify that I inspected the above listed property/unit on 1/6/2023 9:00:00 AM under Title 6, Subtitle 8 of the Environment Article, Annotated Code of MD.

Shannon Scott Bridges

Inspection Contractor Name

13405

Accreditation No.

1/13/2024

Accreditation Exp. Date

Shannon Bridges

Inspector's Name

13404

Accreditation No.

1/13/2024

Accreditation Exp. Date



Inspection certificates with numbers under 1000000 are not original documents; they were issued on paper prior to implementation of this online system.

STATE OF MARYLAND